THE STEADY-STATE SIMULINK MODEL OF THREE-PHASE ASYNCHRONOUS MOTOR USED ONBOARD A SHIP

Paul BURLACU¹ Petrica POPOV² Florentiu DELIU³ Vasile DOBREF⁴ Mitruț C. CARAIVAN⁵

¹Lecturer PhD eng.Naval Academy "Mircea cel Batran", Constanta, vasile.dobref@anmb.ro ²Lecturer PhD Naval Academy "Mircea cel Batran", Constanta, florentiu.deliu@anmb.ro ³Lecturer PhD eng.Naval Academy "Mircea cel Batran", Constanta, paul.burlacu@anmb.ro ⁴Professor PhD eng. Naval Academy "Mircea cel Batran", Constanta, petrica.popov@anmb.ro ⁵PhD eng.Naval Academy "Mircea cel Batran", Constanta, caraivanmitrut@gmail.com

Abstract: A ship plant consisting in a three-phase AC asynchronous motor is well known onboard a ship. The steady-state numerical model helps to study the transitory phenomena's regarding power supply network.

Keywords: asynchronous motor; numerical model

1. Introduction

The three phase asynchronous motor also known as induction machine is a device that is used in almost all electrical applications. This is the reason for such device to be used in naval domain.

The study that is described in the article is based on a 160 Kw three-phase asynchronous motor mathematical model which is implemented in Matlab Simulink. The Asynchronous Machine block implements a three-phase asynchronous machine (wound rotor, single squirrel-cage, or double squirrel-cage). It operates in either generator or motor mode. The state space model is based by the mode of operation that is dictated by the sign of the mechanical torgue:



qaxb

- If torque is positive, the electrical machine is a motor;

- If torque is negative, the electrical machine is a generator.

The mathematical model consists in two types of machines:

• Electrical System of the Wound-Rotor or Squirrel-Cage Machine;

• Electrical System of the Double Squirrel-Cage Machine.

For the study described in the article the wound-rotor system is used. The electrical scheme is presented in fig. 1.



d axls

Figure 1

147

 $V_{\rm qs} = R_{\rm s}i_{\rm qs} + d\varphi_{\rm qs}/dt + \omega\varphi_{\rm ds}$ $V_{\rm ds} = R_{\rm s} i_{\rm ds} + d\varphi_{\rm ds}/dt - \omega \varphi_{\rm ds}$ $V'_{\rm qr} = R'_{\rm r}i'_{\rm qr} + d\varphi'_{\rm qr}/dt + (\omega - \omega_{\rm r})\varphi'_{\rm dr} (1)$ $V'_{\rm dr} = R'_{\rm r}i'_{\rm dr} + d\varphi'_{\rm dr}/dt - (\omega - \omega_{\rm r})\varphi'_{\rm qr}$ $T_{\rm e} = 1.5 p(\varphi_{\rm ds} i_{\rm qs} - \varphi_{\rm qs} i_{\rm ds})$ $V_{\rm qs} = R_{\rm s}i_{\rm qs} + d\varphi_{\rm qs}/dt + \omega\varphi_{\rm ds}$ $V_{\rm ds} = R_{\rm s} i_{\rm ds} + d\varphi_{\rm ds}/dt - \omega \varphi_{\rm ds}$ $0 = R'_{r1}i'_{qr1} + d\varphi'_{qr1}/dt + (\omega - \omega_r)\varphi'_{dr1}$ (2) $0 = R'_{r1}i'_{dr1} + d\varphi'_{dr1}/dt - (\omega - \omega_r)\varphi'_{qr1}$ $0 = R'_{r2}i'_{qr2} + d\varphi'_{qr2}/dt + (\omega - \omega_r)\varphi'_{dr2}$ $0 = R'_{r2}i'_{dr2} + d\varphi'_{dr2}/dt - (\omega - \omega_r)\varphi'_{qr2}$ $T_{\rm e} = 1.5 p(\varphi_{\rm ds} i_{\rm qs} - \varphi_{\rm qs} i_{\rm ds})$

Equations 1 refers to q axis and equations 2 refers to d axis. The electrical part of the machine is represented by a fourth-order state-space model, and the mechanical part by a second-order system. All electrical variables and parameters are referred to the stator, indicated by the prime signs in the following machine equations. All stator and rotor quantities are in the arbitrary twoaxis reference frame (dq frame). The subscripts used are defined in this table 1.

Table 1

Subscript	Definition
d	d axis quantity
q	q axis quantity
r	Rotor quantity (wound-rotor or
	single-cage)
r1	Cage 1 rotor quantity (double-
	cage)
r2	Cage 2 rotor quantity (double-
	cage)
S	Stator quantity
1	Leakage inductance
m	Magnetizing inductance

Table 2	
Parameters common to all models	Definition
Rs, Lls	Stator resistance and leakage inductance
Lm	Magnetizing inductance
Ls	Total stator inductance
V _{qs} , i _{qs}	q axis stator voltage and current

φqs, φdsStator q and d axis fluxesωmAngular velocity of the rotorΘmRotor angular positionpNumber of pole pairsωrElectrical angular velocity (ωm × p)ΘrElectrical rotor angular position (Θm × p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	V _{ds} , i _{ds}	d axis stator voltage and current
ωmAngular velocity of the rotorΘmRotor angular positionpNumber of pole pairsωrElectrical angular velocity (ωm × p)ΘrElectrical rotor angular position (Θm × p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	φ _{qs} , φ _{ds}	Stator q and d axis fluxes
ΘmRotor angular positionpNumber of pole pairsωrElectrical angular velocity (ωm x p)ΘrElectrical rotor angular position (Θm x p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	ωm	Angular velocity of the rotor
pNumber of pole pairsωrElectrical angular velocity (ωm × p)ΘrElectrical rotor angular position (Θm × p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	Θm	Rotor angular position
ωrElectrical angular velocity (ωm × p)ΘrElectrical rotor angular position (Θm × p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	р	Number of pole pairs
wrp) Θ_r Electrical rotor angular position $(\Theta_m \times p)$ T_e Electromagnetic torque T_m Shaft mechanical torque D_m Combined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	ωr	Electrical angular velocity ($\omega_m \times$
ΘrElectrical rotor angular position (Θm × p)TeElectromagnetic torqueTmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient		p)
Or (Θ _m × p) T _e Electromagnetic torque T _m Shaft mechanical torque J Combined rotor and load inertia coefficient. Set to infinite to simulate locked rotor. H Combined rotor and load inertia constant. Set to infinite to simulate locked rotor. F Combined rotor and load viscous friction coefficient	Θr	Electrical rotor angular position
TeElectromagnetic torqueTmShaft mechanical torqueCombined rotor and load inertiaJCoefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient		(Θ _m × p)
TmShaft mechanical torqueJCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to 	Te	Electromagnetic torque
JCombined rotor and load inertia coefficient. Set to infinite to simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient	Tm	Shaft mechanical torque
J coefficient. Set to infinite to simulate locked rotor. H Combined rotor and load inertia constant. Set to infinite to simulate locked rotor. F Combined rotor and load viscous friction coefficient	J	Combined rotor and load inertia
simulate locked rotor.HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient		coefficient. Set to infinite to
HCombined rotor and load inertia constant. Set to infinite to simulate locked rotor.FCombined rotor and load viscous friction coefficient		simulate locked rotor.
H constant. Set to infinite to simulate locked rotor. F Combined rotor and load viscous friction coefficient	Н	Combined rotor and load inertia
Simulate locked rotor. F Combined rotor and load viscous friction coefficient		constant. Set to infinite to
F Combined rotor and load viscous friction coefficient		simulate locked rotor.
friction coefficient	F	Combined rotor and load viscous
	1	friction coefficient

Table 3	
neters	
ific to	

Parameters specific to single-cage or wound rotor	Definition
L'r	Total rotor inductance
R'r, L'ı	Rotor resistance and leakage
	inductance
V'qr, İ'qr	q axis rotor voltage and current
V'dr, İ'dr	d axis rotor voltage and current
φ ' _{qr} , φ ' _{dr}	Rotor q and d axis fluxes

2. Mathematical model description

The performances of the three-phase asynchronous motor that is used onboard of the 8200 tdw cargo ship will be presented starting from this point. The main characteristics for the electrical machine are:

- Voltage: 400 V AC;
- Frequency: 50Hz;
- Rated power: 160 Kw;
- 1500 RPM:
- Stator resistance: 0.01379 ohm:
- Rotor resistance: 0.007728 ohm:
- Stator inductance: 0.000152 H:
- Rotor inductance: 0.000152 H;
- Mutual inductance: 0.00769 H;
- Inertia: 2.9 J;
- Pole number: 2.

3. The Simulink model description

The model that is implemented in matlab Simulink is presented in figure 2 and 3.



Figure 3

The simulation results are presented in the next graphics. Current and voltage values:











CONCLUSION

The mathematical model consists from two parts: electrical model and mechanical model. Both model are simulated in the Matlab Simulink .

The results presented in these two graphs shows that the 160 Kw three-phase asynchronous motor is well fitted for naval purposes. The time response is minimum so transitory phenomena's could not affect the equipment's during period of functioning.

BIBLIOGRAPHY

[1] Popescu M., *Induction Motor Modelling for Vector Control Purposes*, Helsinki University of Technology, Laboratory of Electromechanics, Report, Espoo 2000.

[2] Krause, P.C., O. Wasynczuk, and S.D. Sudhoff, Analysis of Electric Machinery, IEEE® Press, 2002.

[3] Mohan, N., T.M. Undeland, and W.P. Robbins, *Power Electronics: Converters, Applications, and Design*, John Wiley & Sons, Inc., New York, 1995, Section 8.4.1.